

Breakdown of this property's energy performance

Main heating fuel	Grid Supplied Electricity
Building environment	Air Conditioning
Assessment level	3
Building emission rate (kgCO2/m2 per year)	76.84
Primary energy use (kWh/m2 per year)	455

Recommendation report

Guidance on improving the energy performance of this property can be found in the <u>recommendation</u> <u>report (/energy-certificate/9941-4032-0714-0500-2421)</u>.

Contacting the assessor and accreditation scheme

This EPC was created by a qualified energy assessor.

If you are unhappy about your property's energy assessment or certificate, you can complain to the assessor directly.

If you are still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

Accreditation schemes are appointed by the government to ensure that assessors are qualified to carry out EPC assessments.

Assessor contact details

Assessor's name	
Telephone	
Email	

James Penrose 07917198526 jamesp-1983@live.com

Accreditation scheme contact details

Accreditation scheme Assessor ID Telephone Email

Assessment details

Employer Employer address

Assessor's declaration

Date of assessment Date of certificate Sterling Accreditation Ltd STER000520 0161 727 4303 info@sterlingaccreditation.com

Carbon Profile Ltd Unit 2 Long Leys Farm, Leys Road, Oxford, OX2 9QG The assessor is not related to the owner of the property. 22 February 2019 12 March 2019